

POS 15/18

Quick-start guide

en



Printed: 18.12.2014 | Doc-Nr: PUB / 5211229 / 000 / 00

Printed: 18.12.2014 | Doc-Nr: PUB / 5211229 / 000 / 00

QUICK-START GUIDE POS 15/18 total station

1.	First steps	2
1.1	Control panel, touch screen, start menu	2
	Function menu	
1.3	Configuration	3
1.4	Applications	4
2.	Data management	5
	Creating jobs in the measuring system	
2.2	Importing and exporting data	6
3.	Setting up the total station	7
	Stationing the instrument	
3.2	Determining heights	9
4.	Measuring distances, remote heights and areas. Vertical alignment	0
	Measuring distance, height difference and slope	
	Horizontal and vertical area measurement	
	Vertical alignment of building components 1	
	Remote height measurement 1	
	Setting up and laying out using building control lines 1	
	Setting up using control lines 1	
	Laying out using control lines 1	
	Backsighting (creating new fixed points)1	
	Setting a new station by way of backsight points	
6.	Setting up and laying out using points with coordinates	21
	Setting up using points with coordinates	
	Laying out points with coordinates	
	Laying out batter boards (shifting control lines)	
8.	As-built survey with heights	26

1. First steps

1.1 Control panel, touch screen, start menu





2 Display day / night
 3 Functions

- 4 Back to start menu
- 6 Help



Touchscreen

- Instructions and information
- 2 Battery, laser pointer, prism and RL
- 3 Active menu
- 4 Data area
- 5 Illustration
- 6 Data entry fields
- Function buttons

Hilti POS						
Select Task 🛱 📕 🔐						
13.11.14			07:41			
Layout	1 L Meas	Rec	Ref. Line			
As Built	Vert. L	ayout	Applications			
Config	g Info Jo		File			

Function buttons

Buttons to start selected tasks

1.2 Function menu

You can switch to the function menu at any time by pressing the [FNC] button.



- Laser pointer on / off. The laser pointer is used as an aid to make the target point visible. This is useful when taking readings indoors or when laying out.
- Q Guide light on / off. With the aid of the guide light the reflector can be aimed approximately toward the target line.
- O Adjusts display brightness.
- 4 Lets you set the standard target.
- 5 Lets you enter various atmospheric data.
- 6 Shows the electronic level.

1.3 Configuration

Press the [Config] button in the start menu to open the configuration menu.



- Settings for language, units of measurement, angle resolution, decimal separator.
- Control and calibration of the target axis, the V-index and compensator.
- Shows the system information, serial number and software version.
- 4 Touchscreen calibration
- 6 EDM and target settings
- 6 Date and time settings

1.4 Applications

The start menu provides access to several applications. The [Applications] button lets you open additional applications. In this menu, the [Back] button will bring you back to the start menu.





- Lay out design data / points in the area you are working on.
- 2 Lets you take as-built measurements and save points from the coordinate or control line system.
- 3 Measure points relative to a line.
- One of the second se
- 5 Lay out points on a vertical plane.
- 6 Further applications
- Configuration menu
- 8 Job information
- Select jobs
- Copy, import and export jobs and attach DXF files
- CoGo: Calculate using coordinates
- 2 Missing Line: Distance between 2 points
- 3 Area: Measure areas in the horizontal or vertical plane
- 4 Theodolite: Theodolite mode
- 6 Remote Height: Indirect height measurement between two points, one of which cannot be measured directly
- 6 Vert. Align .: Vertical alignment of components
- Dinework: Extract points from a DXF file
- Interface with the Hilti PROFIS Connect software (point transfer)

2. Data management

2.1 Creating jobs in the measuring system

After starting each application you have the possibility of creating a new job or selecting an existing job. It is always necessary to assign an application to a job.



en

2.2 Importing and exporting data

en

[File] is used to manage all jobs held in memory and allows data to be transferred between the total station and a PC. The data origin and the data target to which the data is to be exported must be selected (Int. Mem = total station's internal memory / USB = external memory).



 Return to previous dialog 2 End the dialog 3 Copy data 4 Import data 5 Export data Import DXF data



Copy Job nR Applikation Auswahl>Projekt Base Mem a Int Speich 2 Target Mem Int Speich Job 🚯 ---- ^AB_C New Job

OK

Insert a USB flash drive in the connector provided.

Note

The data on the USB flash drive must be saved in a folder named "Hilti Jobs"

Base Mem: The data origin location (from which the data is to be copied) 1 Target Mem: The data target location (to which the data is to be copied) 2 Projekt: The selected job 3

Hilti POS

Cancel

3. Setting up the total station

3.1 Stationing the instrument

It is necessary to position the total station correctly before making layouts or taking as-built measurements. The position of the instrument (i.e. its station) can then be defined in the form of coordinates or as a position in relation to a building control line (i.e. batter board line).

 Control line: All building components are positioned relative to the dimensions or positioning information given on the control lines in the plan. Using the total station, control lines and their associated dimensions can be used to lay out points.

Stationing anywhere



Stationing using control lines - location over a control line point





 - Coordinates:: On many jobsites there are points with coordinates which have been laid out by a surveyor or the positions of building components, control lines, foundations, etc. may be described by coordinates. In this case, stationing of the system can be set to use coordinates.

Stationing using coordinates - stationing anywhere

Hiti POS
Select Station Type Prim
Prim
Applikation Auswahl>Absteckung/Station setzen
Heights Aus
Point System Koord/Plan
Setup Location Freie Stat
Cancel New H OK



Stationing using coordinates - location over a point





3.2 Determining heights

If you wish to work with heights, the "Heights" setting in the Select Station Type Menu must be set to [0n].

- Setting up the total station over a point with a known height: When the height of the point on the ground is known, the instrument height hi has to be measured.
- Measuring to a point, the height of which is known (benchmark height): The angle and distance to a
 point with known height is measured, so the instrument height is determined by "measuring".



Note:

In the event of using the setting up with building control lines option, the height reference mark must always be entered manually by pressing "Height" then "Man H" and then "Ref. Height". Enter the reference height.

Note:

Setting-up option "Coord./Plan": the height reference mark can <u>also</u> be adopted automatically by selecting the point from memory, by pressing "Height" then "Ref. Height" and then selecting the point with height information.





- Back to previous view
- 2 Manual entry of benchmark height
- Measure to the benchmark height so that the instrument can calculate the station height from this (e.g. if the instrument has not set up using the benchmark height).
- Onfirm the height.
- 6 Select benchmark height (for Coord. / Plan option).
- 6 Enter instrument height hi.
- Denter reflector height hr.
- Cancel operation
- 2 Back to point height
- Measure to the benchmark height so that the instrument can calculate the station height from this (e.g. if the instrument has not set up using the benchmark height).
- 4 Confirm height
- 6 Enter the benchmark height (for building control line option)
- 6 Enter the instrument height hi
- Enter the reflector height hr

4. Measuring distances, remote heights and areas, Vertical alignment.

4.1 Measuring distance, height difference and slope

The [Missing Line] application makes it possible to determine horizontal distance (HD), slope distance (SD), height difference (dH) and the slope between two measured points.





Hilti POS

1. Pkt messen Applikation Auswahl>Spannmass/Pkt mess HR 1 0.400 m 12a ΗА 0° 00' 00" VΔ 90° 00' 00" HD 10.002 m 2 8 Back Next Meas Hilti POS Back 2 Enter or show the attribute assigned to the 2. Pkt messen point Applikation Auswahl>Spannmass/Pkt mess 3 Take the measurement HR 6.000 m 12a 4 Show results HA 0° 00' 00" VΔ 90° 00' 00" HD 10.002 m 6 0 3 Back Line Att Meas Results



[New Ln]: Measure new line 1 [Next Pt]: Measure new second point (2)

10

The [Area] application makes it possible to determine horizontal or vertical areas. This is done by projecting the measured points in the horizontal or vertical plane respectively. The vertical plane is defined by the first two measured points.

Results

Save

4.2 Horizontal and vertical area measurement

Cancel

Hilti POS Save Results

Area

Area

Perim

Perim

No Pts

Back

Del Pt

Applikation Auswahl>Horizontale Fläche/Horiz Fläche

5657.03 m²

0.57 ha

0.33 km

6

6

325.308 m

Hilti POS [Meas]: Take measurement 1 [Results]: Show / save the results (2) DR Measure Area Applikation Auswahl>Horizontale FlächeMessungen 5657.03 m² Area Perim 325.308 m No Pts 6/99

Meas







en

4.3 Vertical alignment of building components

en

The [Vert. Align.] application can be used to align components vertically or to transfer and check verticals

Vert Align







[123]: Enter the reflector height 1 [Meas]: Measure the first point 2

- Go back to measuring the first reference point
- 2 Save the results
- Measure angle and distance and update correction value shown



12

4.4 Remote height measurement

Applikation Auswahl>Indirekte Höhelnd, Höl

0.400 m 122

90° 00' 00"

10.002 m 2

Hilti POS

HR

VA

HD

Measure 1st Pt

The remote height measurement technique can be used to measure height differences between inaccessible positions or points in situations where no direct measurement is Remote Height possible. The height can be read continuously and changes as the vertical angle is adjusted.

DR

3







[123]: Enter the reflector height 1 [Meas]: Measure the first point 2

[Next]: Continue to the next point (3)

5. Setting up and laying out using building control lines

The total station can be set up using existing points on the lines between batter boards (control lines). The zero point of the control line system is typically a previously defined control line intersection (e.g. intersection between axis A and axis 1).





Measuring procedure

Select the desired application. For stationing the instrument using control lines, the **Meas & Rec** and **Batter Board** applications are relevant.

Select the applicable application from the start menu. Before an application can be started, a job must first be selected (see 2.1). The parameters for setting up the instrument station should then be configured. Select **Height OFF**, **Control Line 3 points** and **Station Anywhere**, then press [Next].

Setting up using control lines







1 Enter the reflector height

2 Measure to reference point 1, then continue with point 2

 Enter the reference height
 Measure to reference point 2, then continue with point 3

Enter the reflector height
 Measure to reference point 3

Hilti POS							
Ref. Line	shifts	÷	DR				
Applikation Aus	vahl>Absteck versch.						
Line	0.000 m 1	23					
Offset	0.000 m 1	23					
Height	0.000 m 1	~	Λ				
Rotation	0° 00' 00'' 1	23					
0							
Back			Set 2				

- Back to control line definition
- 2 Confirm the shift values and continue with the entry dialog for Line, Offset and Height values

Note

Press the button beside "Offset" and enter "0". Press [Set] to confirm the offset.

Note

Measure point R1 again in order to check the orientation. The values shown must be: Offset: = 0.00 m

Line: = line offset (example: -2.00 m)

5.2 Laying out using control lines

Hilti POS			
Line to P	oint	÷	DR Prism
Applikation Au	swahl>Querabst	and	
Pt ID			RLL0 ^A B _C
HR		0.	.000 m 123
Line		0.	000 m 123
Offset		0.	000 m 123
Height		0.	.000 m 1 ₂₃
Back	Pt-Line		ок





Enter the layout position as a dimension relative to the defined control line.

The direction and distance to the point to be laid out is shown.

Pivot the instrument until the direction arrow points to "0".

Guide the reflector towards the target and take the measurement.

- 1 Back to the previous dialog
- 2 Take the measurement
- Shows the direction in which the point to be laid out lies
- Enter the reflector height (if the height is being used)
- Back to previous dialog
- 2 Show the result
- 3 Take the measurement
- Gelect the next point

en

5.3 Backsighting (creating new fixed points)

The total station is to be stationed by way of existing points on axes (control lines) between batter boards. A previously defined axis intersection (e.g. intersection between axis A and axis 1) is now to form the zero point of the axis system. Additional fixed points for further building work are also to be measured. These fixed points must be marked and numbered. L

Meas & Rec



Measuring procedure

Select [Meas & Rec] from the main menu.

Before Measure & Register can be started, a job must first be selected (see 2.1). The parameters for stationing the instrument must then be selected. Select **Height OFF**, **Control Line 3 Points**, **Station Any**where and then press **[OK]**.

Hilti POS						
Measure	Points	6				
Applikation Au	swahl>Mes	ssen & Re	gistrieren/N	less & Reg		
Pt ID	1		_	13 ^А в _с		
HR	2		3.000 m 123			
E						
Ν						
н			8			
Cancel	Attr	Dist	M&R	Rec		



en

The newly created fixed points can be used each time the total station is set up in future. Setting up is then carried out using coordinates as the instrument converts the location of the saved points into coordinates.

5.4 Setting a new station by way of backsight points

en

Select the desired application (e.g. Layout) from the start menu. Select the job in which the fixed points were measured.



20

6. Setting up and laying out using points with coordinates

The total station is to be stationed using existing fixed points with coordinates. Fixed points and layout points have already been created in the PROFIS Layout PC application on the basis of a building plan. This data now has to be transferred to the total station and the points created then laid out on the building site.





Measuring procedure

Transfer the data from the USB flash drive to the instrument as already described (see 2.2.). Select the **[Layout]** application in the start menu. Select the applicable job (see 2.1.).

The parameters for stationing the instrument can then be selected: Height OFF, Coord. / Plan, Station Anywhere and then press [OK].

Setting up using points with coordinates



Select the reference point and sight it
 Take the measurement

6.2 Laving out points with coordinates

Hilti POS

Hilti POS								
Select From List 🚔 🚺 Prism								
	likation Aus	wahl>Abst	tec	kung/O	ri Pkt	Messe	n	- 10 1
Pt		1		_	_	_	_	3 ^H B _C
	Pkt	E(Y)		N()	X)	H	I(Z)	
\circ	1	3.000		2.00	0	6.0	000	
$^{\circ}$	2	6.000		3.00	0	2.000		
\circ	3	12.48	9	5.16	63			
2								
Cancel Map List Man				an	C	ĸ		

The point to be laid out can be selected from the list or plan or entered manually.

 Confirm the coordinates 2 Confirm the coordinates

The direction and distance to the point to be laid out will be shown

- Return to the previous dialog.
- 2 Take the measurement. Guide the reflector towards the target and take the measurement.
- 3 Shows the direction in which the point lies. Pivot the instrument until the direction indicator arrow points to "0".
- 4 Enter the reflector height (if the height is being used).)
- Return to the previous dialog.
- 2 Deviations in the X and Y directions (can be saved)
- 3 Take the measurement again.
- Select a new layout point.



nR



7. Laying out batter boards (shifting control lines)

The total station is to be stationed using existing fixed points with coordinates. On the building site there are control lines to be laid out, extended or shifted parallel, e.g. on batter boards or on floor slabs. The building plan has been processed using PROFIS Layout and the points on the control lines have been saved in the total station in the form of coordinates.



Line Point L1

Measuring procedure

Transfer the data from the USB flash drive as described (see 2.2). Select the **[Batter Board]** application from the main menu. Select the applicable job (see 2.1.).

Next, select the parameters to be used for stationing the instrument: **Height OFF**, **Coord**. / **Plan**, **Station Anywhere** and then press **[OK]**. Carry out the procedure for stationing the instrument as already described (see 7.) and then set the station.



Hilti POS			
Ref. Line	shifts	ŝ	DR Prism
Applikation Aus	wahl>Absteck versch.		
Line	0.000 m 12	3	
Offset	0.000 m 12	3	
Height	0.000 m 12	23	∧
Rotation	0° 00' 00'' 12	23	
			$ \rightarrow $
Back			Set 🚺

- Select the building control line directly from the plan.
- 2 Define the control line by selecting 2 points.
- 3 Measure the control line.
- Ocnfirm the dialog.

The reference control line is defined by the two points on the line. In addition, these can optionally be shifted by a given value in the offset or line directions.

1 Confirm the selection and continue.

After defining the reference control line, the positions of points relative to this line can then be specified. Points already saved in the instrument, for example, can be converted so that their position is defined relative to this line. Points can also be measured. The line and offset values for positions relative to the defined line are shown in the display.

8. As-built survey with heights

The total station is to be used to make an as-built survey. This could be, for example, a survey of the facade of a building, the path followed by a road or the excavations for the foundations of a building. The survey is required for planning purposes. All planning of things such as facade components, road boundaries or volume calculations is carried out on the basis of the data obtained from the survey.





Measuring procedure

Analyze the object and decide where the instrument is to be stationed. Fixed points for stationing the instrument are required for each station. Before beginning the measuring procedure, fixed points must be assigned around the object to be surveyed and marked accordingly.

Select the [Meas & Reg] application from the start menu. Create a new job (see 2.1.).

Define the parameters to be used for stationing the instrument: Height ON, Control Lines, Station Anywhere and then press [OK].

Carry out the stationing procedure for the instrument as already described (see 6.) and set the station.



Hilti POS

н

HR Stat H

61

Cancel

Enter BM Height

BM Height 5

Applikation Auswahl>Absteckung/BM Höhe messen

6

2

PtH

0.000 m 12

0.000 m 12

6

Meas

- Back to the previous dialog.
- 2 Take the measurement to the reference point.
- Onfirm the dialog.
- 4 Select the reference point.
- Specify the height of the reflector.
- 6 Shows the already measured reference points and the differences.

- Back to the previous dialog.
- 2 Select the height above the point.
- 3 Take the measurement.
- 4 Confirm the dialog.

DR

4

OK

- Select the point (benchmark height).
- 6 Specify the height of the instrument.
- Specify the height of the reflector.

- Hilti POS Measure Points Applikation Auswahl>Messen & Registrieren/Mess & Reg Pt ID 1 11 ^AB_c HR 3.000 m 122 Е Ν н 2 Cancel Attr Dist M&R Rec
- Enter the names of the points.
 Measure and save the result.

All of the required points can subsequently be measured from the first instrument station. When moving to a different station, the instrument must be set up as usual, levelled and the [Meas & Reg] application then started. Confirm the job that was started from the first instrument station. It is not possible to re-station the instrument using control lines. The total station converts all of the points measured in the job into coordinates (see 6.1.). Orientation is then carried out by way of coordinate points as already described. Once the new station has been set, the survey can be continued.



Hilti Corporation

LI-9494 Schaan Tel.: +423/2342111 Fax: +423/2342965 www.hilti.com



Hilti = registered trademark of Hilti Corp., Schaan Pos. 1_en | 20141215